

Large Format Air Tight Barrier Cover

Machinery is packaged by hermetically through-bolting through the base of the barrier cover to a custom export skid. After the machinery is securely fastened to the export pallet VCI emitters and or desiccants are placed into machine cavities as needed and the top half of the barrier cover is placed over the machine and heat sealed to the base of the cover. Air is then evacuated from the cover to finish the packaging process. This application required hermetic sealing around lifting trunions in addition to hermetic through-bolting to the export skid.

